F-Chart Software

Mastering EES

Sanford Klein and Gregory Nellis





Stroke = 75 [mm]
Bore = 130 [mm]
Displacement = 0.9955 [l]

CompressionRatio = 18 Efficiency = 0
RPM = 3000 [1/min] Power = 0 [kW]
CutoffRatio = 2 T_{max} = 0 [K]

#10 Run 14







TABLE OF CONTENTS